

**SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 21-Nov-14

Time 10:09 PM

**Daily Diary Report by Bid Item**

Contract No.: 04-0120F4

Diary #: 176 Const Calendar Day: 80

Date: 23-Aug-2012 Thursday

Inspector Name: Altamirano, Victor

Title: Transportation Engineer

Inspection Type:

Shift Hours:

Break:

Over Time:

Federal ID:

Location:

Reviewer: Schmitt, Alex

Approved Date:

Status: Submit

**04-0120F4  
04-SF-80-13.2/13.9  
Self-Anchored  
Suspension Bridge****Weather****Temperature** 7 AM 50 - 60 12 PM 50 - 60 4PM 50 - 60**Precipitation****Condition**Working Day ☒ If no, explain:**Diary:**

Dispute

**Work description.**

## Field Work:

(1) I went out to the SAS in the morning to verify the painting on the suspender sockets given that there was a concern about paint damage to one of the sockets. It was determined that the damaged socket was at PP 82N and it had paint/galvanizing damaged. I did not see any cable work while I was in the field.

## Office Work:

(1) Updated my cable band checklist log and provided it to other CT inspectors.

My work hours: 8 hours total.

